Technical Committee - 20th September 2016

SKYbrary Update Requests to review/endorse articles

AP Ref	Title	Web address	Remarks
G068	Piston Engine Induction Icing	http://www.skybrary.aero/index.ph p/Piston_Engine_Induction_Icing	Needs ONE MORE REVIEWER to complete the review
G069	VFR Flight Into IMC	http://www.skybrary.aero/index.ph p/VFR_Flight_Into_IMC	Reviewed & amended by Instructors WG
G070	Engine Failure After TakeOff - Light Twin Engine Aircraft	http://www.skybrary.aero/index.ph p/Engine Failure After TakeOff - Light Twin Engine Aircraft	Needs TWO MORE REVIEWERS to complete the review
G071	Rules of Thumb	http://www.skybrary.aero/index.ph p/Rules of Thumb	Submitted but still rather simplistic - any offers of additional 'rules of thumb worth sharing?
G072	Rapid Disembarkation	http://www.skybrary.aero/index.ph p/Precautionary Rapid Disembar kation	Reviewed & amended by AP SKYbrary team
G073	Cross Wind Takeoffs	http://www.skybrary.aero/index.ph p/Cross Wind Takeoff Hazards and Techniques	AP suggested numerous changes to first draft. Would benefit from a fresh look by THREE new reviewers
G074	Night Vision Imaging System (NVIS)	http://www.skybrary.aero/index.ph p/Night Vision Imaging System (NVIS)	New request – needs THREE REVIEWERS
G075	Rejected Takeoff	http://www.skybrary.aero/index.ph p/Rejected_Take_Off	New request – needs THREE REVIEWERS

See also http://www.skybrary.aero/index.php/The_Honourable_Company_of_Air_Pilots listing over fifty SKYbrary articles under Air Pilots' 'Content Control'. These have already been edited and improved and then endorsed by the Air Pilots. Even so, we, we recognised at the time of endorsement that many were still only 'adequate' rather than being exemplar. We have an agreement to review and update these from time to time. TC members are welcome to review any of the articles under Air Pilots' Content Control and to send amendment suggestions to DAA at any time.

DAA 11 September 2016